


# DRILL BUSH WITHOUT COLLAR

DIN 179 (similar ISO 4247)

type A: Bore hole rounded at one end



$$\sqrt{Rz\ 25} \left( \sqrt{Rz\ 4} \right)$$

## Item no.

7819.

## Hardness

HRC 62 + 2

## Material

Case-hardened steel as chosen by manufacturer.

Inside and outside grinded in tolerance, with insertion chamfer.

<b>d<sub>1</sub></b> <b>F7</b>	<b>l1</b>	<b>d<sub>2</sub></b> <sup>1)</sup> <b>n6</b>	<b>r</b>	<b>tr</b>	<b>7819</b>
0.6-1	6	3	1	0,01	•
0.9-1	9	3	1	0,01	•
1.1-1.8	6	4	1	0,01	•
1.1-1.8	9	4	1	0,01	•
1.9-2.6	6	5	1	0,01	•
1.9-2.6	9	5	1	0,01	•
2.7-3.3	8	6	1	0,01	•
2.7-3.3	12	6	1	0,01	•
2.7-3.3	16	6	1	0,01	•
3.4-4	8	7	1	0,01	•
3.4-4	12	7	1	0,01	•
3.4-4	16	7	1	0,01	•
4.1-5	8	8	1	0,01	•
4.1-5	12	8	1	0,01	•
4.1-5	16	8	1	0,01	•
5.1-6	10	10	1,5	0,02	•
5.1-6	16	10	1,5	0,02	•
5.1-6	20	10	1,5	0,02	•
6.1-8	10	12	1,5	0,02	•
6.1-8	16	12	1,5	0,02	•
6.1-8	20	12	1,5	0,02	•
8.1-10	12	15	2	0,02	•
8.1-10	20	15	2	0,02	•
8.1-10	25	15	2	0,02	•
10.1-12	12	18	2	0,02	•
10.1-12	20	18	2	0,02	•
10.1-12	25	18	2	0,02	•
12.1-15	16	22	2	0,02	•
12.1-15	28	22	2	0,02	•
12.1-15	36	22	2	0,02	•
15.5-18	16	26	2	0,02	•
15.5-18	28	26	2	0,02	•

<b>d<sub>1</sub></b> <b>F7</b>	<b>l1</b>	<b>d<sub>2</sub>) n6</b>	<b>r</b>	<b>tr</b>	<b>7819</b>
15.5-18	36	26	2	0,02	.
18.5-22	20	30	3	0,02	.
18.5-22	36	30	3	0,02	.
18.5-22	45	30	3	0,02	.
22.5-26	20	35	3	0,02	.
22.5-26	36	35	3	0,02	.
22.5-26	45	35	3	0,02	.
26.5-30	25	42	3	0,02	.
26.5-30	45	42	3	0,02	.
26.5-30	56	42	3	0,02	.
30.5-35	25	48	3	0,02	.
30.5-35	45	48	3	0,02	.
30.5-35	56	48	3	0,02	.

**1) For drilling with tolerance range H 6 or H 7 in jig/fixtures.**

**Gradation of the bore hole d<sub>1</sub> until 22,0 of 0,1 mm > 22,0 of 0,5 mm.**


**Type B (Bore hole rounded at both ends)=10% surcharge.**



# DRILL BUSH WITH COLLAR

DIN 172 (similar ISO 4247)

type A: Bore hole rounded at one end



**Item no.**

7619.

**Hardness**

HRC 62 + 2

**Material**

Case-hardened steel as chosen by manufacturer.

Inside and outside grinded in tolerance, with insertion chamfer.

<b>d<sub>1</sub></b> F7	<b>l1</b>	<b>d<sub>2</sub></b> <sup>1)</sup> n6	<b>d3</b>	<b>l2</b>	<b>r</b>	<b>tr</b>	<b>tp</b>	<b>7619</b>
0.6-1	6	3	6	2	1	0,01	0,03	•
0.9-1	9	3	6	2	1	0,01	0,03	•
1.1-1.8	6	4	7	2	1	0,01	0,03	•
1.1-1.8	9	4	7	2	1	0,01	0,03	•
1.9-2.6	6	5	8	2	1	0,01	0,03	•
1.9-2.6	9	5	8	2	1	0,01	0,03	•
2.7-3.3	8	6	9	2,5	1	0,01	0,03	•
2.7-3.3	12	6	9	2,5	1	0,01	0,03	•
2.7-3.3	16	6	9	2,5	1	0,01	0,03	•
3.4-4	8	7	10	2,5	1	0,01	0,03	•
3.4-4	12	7	10	2,5	1	0,01	0,03	•
3.4-4	16	7	10	2,5	1	0,01	0,03	•
4.1-5	8	8	11	2,5	1	0,01	0,03	•
4.1-5	12	8	11	2,5	1	0,01	0,03	•
4.1-5	16	8	11	2,5	1	0,01	0,03	•
5.1-6	10	10	13	3	1,5	0,02	0,03	•
5.1-6	16	10	13	3	1,5	0,02	0,03	•
5.1-6	20	10	13	3	1,5	0,02	0,03	•
6.1-8	10	12	15	3	1,5	0,02	0,03	•
6.1-8	16	12	15	3	1,5	0,02	0,03	•
6.1-8	20	12	15	3	1,5	0,02	0,03	•
8.1-10	12	15	18	3	2	0,02	0,03	•
8.1-10	20	15	18	3	2	0,02	0,03	•
8.1-10	25	15	18	3	2	0,02	0,03	•
10.1-12	12	18	22	4	2	0,02	0,03	•
10.1-12	20	18	22	4	2	0,02	0,03	•
10.1-12	25	18	22	4	2	0,02	0,03	•
12.1-15	16	22	26	4	2	0,02	0,03	•
12.1-15	28	22	26	4	2	0,02	0,03	•
12.1-15	36	22	26	4	2	0,02	0,03	•
15.5-18	16	26	30	4	2	0,02	0,03	•
15.5-18	28	26	30	4	2	0,02	0,03	•

<b>d<sub>1</sub></b> <b>F7</b>	<b>l1</b>	<b>d<sub>2</sub><sup>1)</sup></b> <b>n6</b>	<b>d3</b>	<b>l2</b>	<b>r</b>	<b>tr</b>	<b>tp</b>	<b>7619</b>
15.5-18	36	26	30	4	2	0,02	0,03	.
18.5-22	20	30	34	5	3	0,02	0,03	.
18.5-22	36	30	34	5	3	0,02	0,03	.
18.5-22	45	30	34	5	3	0,02	0,03	.
22.5-26	20	35	39	5	3	0,02	0,05	.
22.5-26	36	35	39	5	3	0,02	0,05	.
22.5-26	45	35	39	5	3	0,02	0,05	.
26.5-30	25	42	46	5	3	0,02	0,05	.
26.5-30	45	42	46	5	3	0,02	0,05	.
26.5-30	56	42	46	5	3	0,02	0,05	.
30.5-35	25	48	52	5	3	0,04	0,05	.
30.5-35	45	48	52	5	3	0,04	0,05	.
30.5-35	56	48	52	5	3	0,04	0,05	.

**1) For drilling with tolerance range H 6 or H 7 in jig/fixtures.**

**Gradation of the bore hole d<sub>1</sub> until 22,0 of 0,1 mm > 22,0 of 0,5 mm.**

**Type B (Bore hole rounded at both ends)= 10% surcharge.**

